STANDARD DEPARTURE CHART - INSTRUMENT (SID) - ICAO

TRANSITION LEVEL by ATC
TRANSITION ALTITUDE *7000*

ZURICH (LSZH)
RNAV RWY 34

DEGES 4H GERSA 1H



COMMUNICATION FAILURE PROCEDURE:

- Set transponder on code 7600.
- Cross DEGES / GERSA climbing to / at last received and acknowledged FL but not below MCA**.
- Continue climb to FPL FL.

** Leave last received and acknowledged FL or ALT earliest three minutes after airborne.

THIS PAGE INTENTIONALLY LEFT BLANK