STANDARD INSTRUMENT DEPARTURE CHART
(SID) - ICAO

TRANSITION LEVEL by ATC
TRANSITION ALTITUDE *7000*

ZURICH LSZH
SID RWY 32 - RNAV 1
(by ATC only)



COR: note (WEF 18MAY2023)

COMMUNICATION FAILURE PROCEDURE:

- Set transponder on code 7600.
- CrossDEGES climbing to/at last received and acknowledged FL but not below MCA*.
- Continue climb to FPL FL.

*) Leave last received and acknowledged FL or ALT earliest three minutes after airborne.

THIS PAGE INTENTIONALLY LEFT BLANK