


STANDARD DEPARTURE CHART -
INSTRUMENT (SID) - IACO

TRANSITION LEVEL by ATC
TRANSITION ALTITUDE 7000

ZURICH (LSZH)
RNAV RWY 10

DEGES 3E GERSA 3C GERSA 2E VEBIT 4E ZUE 1E



COMMUNICATION FAILURE PROCEDURE:

- Set transponder on code 7600.
 - Cross DEGES / GERSA / VEBIT / ZUE climbing to/at last received and acknowledged FL but not below MCA*.
 - Continue climb to FPL FL
- *) Leave last received and acknowledged FL or ALT earliest three minutes after airborne

THIS PAGE INTENTIONALLY LEFT BLANK